

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer HASEENA. A
2. Name of the School St. Thomas Central School, Thottappally
3. Location with name of Education District/ Sub. District Alappuzha, Ambalapuzha Sub. Dist.
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.
1. 33.60 x 9.0 x 3.60 m Rec 2nd Floor
2. 33.60 x 9.0 x 3.60 m Rec First Floor
3. 33.60 x 9.0 x 3.60 m Rec Ground Fl
5. Period for which the certificate is issued 2023-2024 Academic year
6. Nature of defects, if any
a) Foundation and basement NIL
b) Superstructure NIL
c) Doors and Windows NIL
d) Wood work wrought and put up NIL
e) Roof NIL
f) Flooring NIL
g) Miscellaneous (Cracks, etc.) NIL
7. Any major defects noticed which will render the building unsafe in any manner NIL
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes Sound under normal weather condition only

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 17/6/23 and found to be fit / unfit to conduct classes, for the period 2023-2024 for the reasons stated above.

Place: Karuratha

Date: 17/6/23

Principal
St. Thomas Central School
Thottappally PO, Alappuzha
Pin: 688 561, Kerala, India



Assistant Engineer
L.I.D. & E.W.
Assistant Engineer
KARURATHA